

Building Safety Certificate

It is certified that our inspection team headed by Mr. Ravi Prakash,

_____ inspected the **The Garden International School, Sherpur, Patna** and found that the structure and building is safe for occupancy.

The below mentioned are the details of concerned property:

Name of Trust/Society: Sanskat Educational Trust
Name of the School: The Garden International school.
Address of Property: Danapur Near Main Road
Near H.P. Gas Agency
Sherpur Patna - 801503

Signature with seal Ravi

Name: Ravi Prakash

Designation: S-E.

Date: 24.05.23 **J.E.**
Nagar Parishad Danapur Nizamat

To,

The Garden International School

Sherpur, Danapur, Patna, Bihar

Pin: 801503